

**TV INSPECTION OF SWEETWATER SUBDIVISION Township 29 Section 17 Range 12**

Sys #	Location	Size	From	To	Inspected Length	Total Length of Pipe	Completed	Comments	Resolution & Repair
1	4305 Saltwater Boulevard	15" RCP	INCI000051	INCI000052	151.2	154.0	5/15/2003	Lift hole leaking at 31ft and 47ft. Pipe deterioration at 112.5ft	Chemical Grouted 10/26/04 Specialized Services
1A	4307 Saltwater Boulevard	15" RCP	INCI000052	MSET000063	106	138.0	5/28/2003	No problem in system	
2	4220 Saltwater Boulevard Deepwater Lane	15" RCP	INCI000047	INCI000049	59.4	92.0	5/29/2003	Camera blocked by rock in pipe	Rocks removed by WSU Jet Truck 10/20/04
2A	4220 Saltwater Boulevard Deepwater Lane	15" RCP	INCI000047	INCI000046	36.1	36.1	5/29/2003	No problem in system	
2B	4220 Saltwater Boulevard Deepwater Lane	15" RCP	INCI000047	MNHL000010	41.4	41.4	5/29/2003	No problem in system	
2C	4215 Deepwater Lane	15" RCP	MNHL000010	MSET000042	60.1	190.0	6/2/2003	Blockage of rocks in system	Rocks removed by WSU Jet Truck 10/20/04
3	4205 Deepwater Lane	15" RCP	INCI000002	INCI000008	27.3	27.3	6/2/2003	No problem in system	
3A	4205 Deepwater Lane	15" RCP	INCI000008	MSET000075	104	132.0	6/2/2003	No problem in system	
4	4215 Saltwater BL	15" RCP	INCI000082	INCI000044	27.9	27.9	6/3/2003	No problem in system	
4A	4215 Saltwater BL	15" RCP	INCI000044	MSET000046	86	140.0	6/3/2003	No problem in system	
5	4173 Saltwater BL	15" RCP	INCI000014	INCI000015	24.1	24.1	6/3/2003	No problem in system	

TV INSPECTION OF SWEETWATER SUBDIVISION Township 29 Section 17 Range 12

5A	4173 Saltwater BL	18" RCP	INCI000015	MSET000074	110.5	158	6/3/2003	Leaking joints and lift holes discovered 10/20/04	Chemical Grouted 10/27/04 Specialized Services
6	4149 Saltwater BL	15" RCP	INCI000010	INCI000018	31.6	31.6	6/3/2003	No problem in system	
6A	4149 Saltwater BL	18" RCP	INCI000018	MSET000028	149.5	152	6/3/2003	Joint seems to be separated at 134ft. Joint is offset and separated at 142ft	TMD/West Service Unit Inserted ADS Liner November 2004
7	4120 Saltwater Boulevard Crosswater Avenue	15" RCP	INCI000040	INCI000020	72	72	6/3/2003	No problem in system	
7A	4120 Saltwater Boulevard Crosswater Avenue	15" RCP	INCI000040	INCI000069	28.8	28.8	6/3/2003	No problem in system	
7B	4119 Saltwater BL	24" RCP	INCI000069	MSET000002	136.8	136.8	6/3/2003	No problem in system	